



100

Fig. 1






[illegible]

Fig 3




Fig 4




Fig 5




Fig. 6




Fig. 8





Fig. 9






Fig. 11




Fig. 12




Fig 13




Fig. 14




Fig. 15





Fig 16






Fig. 18




Fig. 19




Fig. 20




Fig. 21

106280" 9E224660




Fig. 22




Fig. 23




Fig. 24




Fig 25

TOP SECRET

T.P. 194

Balloon

Balloon Retraction
Subassembly

192

120

236

238

Cable Cap

Tube shown
cut in half.

234

236


120

Fluid

Note:

A cable connects the "Tip"
to the "Cable Cap".

Fig 26






Fig 27




Fig 28




Fig 29




Fig 30




Fig 31




Fig. 32




Fig 33




Fig 34




Fig 35




Fig 36

Fig. 37




Fig 38



